


Silicone 3D -500-



Recommended Fabrics

100% cotton
100% polyester*
Poly/cotton blends

Cutting Notes

You should always test cut prior to any production run. Remember cutter settings will need to be adjusted as your blade ages. For optimal cutting and weeding, maintain a line thickness of at least 2.0 mm for lettering & logos.

Application Instruction

Temp: 150°C
Time: 10 seconds
Pressure: Medium
(#4-6 on Hotronix®)
Peel: Cold

Multi-Colour Designs

CAD-CUT® Silicone 3D -500- is not recommended for multilayered applications.

Care Instructions

Machine wash warm up to 60°C mild detergent.
Do not use bleach.
Dry at a normal dryer setting on household machines.
Do not dry clean.
Can be directly ironed onto.

Storage

Store in a cool, dry area.
Avoid direct heat, sunlight and humidity.

Accessories Required

Craft Paper or Reusable Cover Sheet
EZ Weeder®

* Always test before manufacture.

STAHL'S



KEY

